

CREATIVE

# Woodturning



DALE L. NISH

# Contents

Foreword	vii
The Wood Lathe	1
Measuring and Layout Tools	8
Lathe Tools	11
Sharpening Turning Chisels	13
A Controversy: Which Method, Cutting or Scraping?	23
Stock Selection and Preparation for Turning	25
Turning Stock Between Centers: Centering and Mounting the Stock	29
Turning Stock Between Centers: Gouge-Turning a Cylinder	33
Smoothing a Cylinder	36
Turning Between Centers: Using the Parting Tool for Cutting to Length	39
Spindle Turning: Cutting Coves, Scraping Method	41
Spindle Turning: Cutting Beads, Scraping Method	44
Turning Stock Between Centers: Using a Gouge to make Coves or Grooves	46
Turning Between Centers: Making Beads with Skew Chisel, Cutting Method	50
Cutting V-Grooves	55
Cutting and Smoothing Shoulders	57
Spindle Turning: Cutting a Taper	59
Turning Between Centers: Turnings with Rectangular Sections	63
Duplicate Turnings	71
Faceplate Turning: Centering and Mounting the Stock on a Metal Faceplate	75
Fastening Stock to a Faceplate, Glue Method	78
Glue Chucking	80
Ring Clamp Chuck	83
Faceplate Turning: Reducing to Outside Diameter	86
Boring	88
Sanding	91
Finishing Wood Turnings	95
Oval Turnings	101
Split Turnings	105
Working with Unseasoned Wood	109
Turning a Deep Bowl	117
Turning a Shallow Bowl	125
Rectangular Trays	129
Shaping after Turning	133
Lids	134
Small Round Boxes	140
Turning Pepper Mills	145
Segmented Ring Construction	149
Laminated Bowls	155
Stave Construction	165
Turning Goblets	173
Project: Candle Lamps	191
Project Section	203
Author and Consultant	246
Index	247