

## **Rapid KL Monorail Service Resumes Operations**

**Bernama**

**Mar 30, 2015**

KUALA LUMPUR, March 30 (Bernama) -- The Rapid Rail monorail service resumed this afternoon but operating on degraded mode due to faults of the signalling system.

The service was earlier suspended following two incidents this morning, one of which concerned one of the rubber tyres of a two-car train which caught fire at the Titiwangsa station.

The fire which caused heavy smoke at the station was put out by the Fire and Rescue Department, according to a statement from Rapid Rail Monorail Line chief operating officer Abdul Hadi Amran.

He clarified that it involved a two-car train, not a four-car train as earlier stated.

The statement also mentioned that the second incident which prompted the suspension involved a four-car train which became stranded between the Imbi and Bukit Bintang stations due to technical problems.

An earlier statement said that it involved a two-car train.

"Rapid Rail is carrying out an internal investigation into both incidents and apologised for the inconvenience caused," Abdul Hadi said.

-- BERNAMA

Copyright © 2015 BERNAMA

Source : <http://www.bernama.com/bernama/v8/newsindex.php?id=1121360>