


# The Practice of

---

# WOODTURNING

---

Mike Darlow



Pratt  
Burns  
P  
E34184

# Contents

Preface	ix
Acknowledgments	xi
Terminology	xii
<b>1 WOOD</b>	<b>1</b>
1.1 Tree and Wood Nomenclature	1
1.2 Tree Growth	4
1.3 Chemical Composition of Wood	5
1.4 Types of Extractives	6
1.5 Effects of Extractives on Wood Properties	6
1.6 Strength, Moisture Content, and Temperature	6
1.7 Fungal and Insect Attack	9
1.8 Intentional Staining	11
1.9 Turnability	11
1.10 Sources of Wood	12
<b>2 DESIGN</b>	<b>13</b>
2.1 The Production of a Design	14
2.2 Sources of Design	14
2.3 Treen	15
2.4 Design Nomenclature	15
2.5 The Physical Process of Designing	24
2.6 Design Guidelines	24
2.7 Aesthetic and Practical Considerations	27
2.8 Suitability for Use	28
2.9 Influences and Limitations on Design	28
2.10 Style, Fashion, and Taste	29
2.11 Marketing	30

<b>3</b>	<b>THE LATHE</b>	<b>32</b>
3.1	History of the Lathe	33
3.2	Types of Lathe	34
3.3	Lathe Capacity	36
3.4	The Lathe Bed	37
3.5	The Stand	38
3.6	The Headstock	40
3.7	The Tailstock	43
3.8	Tailstocks for Long-hole Boring	44
3.9	The Banjo	46
3.10	Toolrests	47
3.11	Motor, Transmission, and Switch Gear	49
3.12	Driving Centers	50
3.13	Tail Centers	52
3.14	Outboard Turning Stands	52
3.15	The Carriage	54
<b>4</b>	<b>LATHE ACCESSORIES AND ASSOCIATED EQUIPMENT</b>	<b>56</b>
4.1	Measuring Equipment	56
4.2	Faceplates	58
4.3	Screwchucks	59
4.4	Cupchucks	60
4.5	Jacobs Chucks	61
4.6	Sleeves	61
4.7	Engineer's Chucks	62
4.8	Collet Chucks	67
4.9	Recently Introduced Chucks	69
4.10	Homemade Chucks	69
4.11	Vacuum Chucks	72
4.12	Mandrels	72
4.13	Drill Bits	75
<b>5</b>	<b>TURNING THEORY AND TOOLS</b>	<b>77</b>
5.1	Cutting Theory	77
5.2	Tool Steels	82
5.3	The Roughing Gouge	83
5.4	The Skew Chisel	86

- 5.5 The Detail Gouge 89
- 5.6 The Parting Tool 94
- 5.7 Scrapers 95
- 5.8 Recommended Set of Tools 97
- 5.9 Tool Handles 97
- 5.10 Making Handles 98
- 5.11 Other Tools 99
- 5.12 Tool Grinding 101
- 5.13 Honing 108

## 6 WORKSHOP PROCEDURES 110

- 6.1 Workshop Safety 110
- 6.2 Lighting 111
- 6.3 The Stance 113
- 6.4 Turning Grips 113
- 6.5 Small-scale Turning 118
- 6.6 Turning Other Materials 118
- 6.7 Turning for Furniture Restoration 119
- 6.8 Sanding 120
- 6.9 Finishing 126

## 7 SPINDLE TURNING 128

- 7.1 Pencil and Pin Gauges 128
- 7.2 Preparation of Wood for Turning 133
- 7.3 Mounting the Wood Between Centers 136
- 7.4 Principles of Spindle Turning 138
- 7.5 Roughing 143
- 7.6 V-cuts 149
- 7.7 Leaving Squares 150
- 7.8 The Planing Cut 155
- 7.9 Bead Cutting 158
- 7.10 Cutting Fillets 180
- 7.11 Removing Waste with the Skew 180
- 7.12 Squaring Shoulders 180
- 7.13 Parting Tool Work 183
- 7.14 Use of the Detail Gouge 183
- 7.15 Parting-off 192
- 7.16 Copy Turning 194
- 7.17 Slender Turning 194

- 7.18 Split Turnings 200
- 7.19 Multiple-axis Turning 201
- 7.20 Laminating 208
- 7.21 Twists, Spirals, Fluting, and Reeding 208
- 7.22 Exercises 209

## 8 CUPCHUCK TURNING 214

- 8.1 Fixing the Work to the Headstock 214
- 8.2 Cupchucking a Knob 216
- 8.3 Turning an Egg Cup 220
- 8.4 Turning Lidded Boxes 225
- 8.5 Hollow Turning 233

## 9 FACEPLATE AND BOWL TURNING 234

- 9.1 Bowl Design 235
- 9.2 Wood for Bowls 239
- 9.3 Wood Preparation for Rough-turning of Bowls 240
- 9.4 The Effect of Tool Choice and Presentation 253
- 9.5 The Near-vertical Inclination 262
- 9.6 The Near-horizontal Inclination 264
- 9.7 Going Round-the-bend 265
- 9.8 Gouge Cross-sections and Sharpening 266
- 9.9 Scrapers in Bowl Turning 271
- 9.10 Faceplate Turning 271
- 9.11 Bowl Design and Chucking 289
- 9.12 Bowl Rough-turning 289
- 9.13 Mounting the Disk on the Lathe for Roughing 291
- 9.14 Single-operation Roughing 291
- 9.15 Two-operation Roughing 305
- 9.16 Seasoning 310
- 9.17 Stabilization 311
- 9.18 Finish-turning 312
- 9.19 Holding by the Rim 318
- 9.20 Bowl Sanding 329
- 9.21 Bowls from Wet Wood 331
- 9.22 Waney-edged Bowls 331

Gallery	335
Index	355